DNA Analysis of Building

DNA Mould Test



Address Ásgarður, Garðabær

Case nr. 3.161.345

Requester Mannvit hf, Alma Dagbjört

Lab nr. 2023000546

Test ID 7188 og 7189

Sample date 31.01.2023 Receipt date 03.02.2023 Analysis date 08.02.2023



7188 Ásgarður, Garðabær sportshall, basketball, top of cencretepole, 295

DNA tests may reveal whether there are microorganisms (mould) in dust originating from moisture damaged building materials or concealed water damages. Microbiologic material from concealed constructions may over time be released to the residential zone, where it will sediment with the dust. The result of the DNA analysis is an indication of the extent of which the room is affected by microbiologic material.

CONCLUSION

Based on the analysis results for the test made from sportshall, basketball, top of cencretepole, Ásgarður, Garðabær, our evaluation is that the rate of mould in the building is somehow above the normal, expected level for dry, clean and undamaged buildings. When looking at the composition of mould species there is no sign of a severe or long-lasting moisture damage. The slightly increased level of total mould is primarily attributed to accumulation in dust by outdoor species. However, there is an increased level of *Penicillium* and *Aspergillus*, which may originate from a small moisture damage with low moisture levels, as e.g. condensation on a thermal bridge.

We recommend to dry off horizontal surfaces and to vacuum with a HEPA filter.

However, we would like to point out that the evaluation is merely based on the analysis results. As the results only form part of our evaluation basis, these results should always be compared to observations and moisture measurings on site, before drawing a final conclusion.



The mould level is normal, and there are no indications of concealed moisture damages.

Furthers actions are not necessary.

The mould level is slightly increased, which may indicate an old dried-out damage or cumulation of fungi material in dust.

Small renovations must be expected, or cleaning according to further instructions.

The occurrence of mould is abnormal, which indicates a severe and/or long-term water damage.

A big renovation work must be expected, which means to find and eliminate the source of moisture, to determine the extent of the damage and to draw up a plan of action for the renovation.



7188 Ásgarður, Garðabær sportshall, basketball, top of cencretepole, 295

RESULT

Mængden af organismer pr. cm²

Total antal skimmelsvamp	16857	100,00%
Wallemia sebi	0	0,00%
Cladosporium cladosporioides	419	2,49%
Cladosporium herbarum	320	1,90%
Cladosporium sphaerospermum	451	2,68%
Mucor/Rhizopus grp.	0	0,00%
Rhizopus stolonifer	0	0,00%
Acremonium strictum	0	0,00%
Aspergillus og Penicillium arter	2793	16,57%
Aspergillus fumigatus	0	0,00%
Penicillium chrysogenum	0	0,00%
Tricoderma viride	0	0,00%
Aspergillus glaucus	0	0,00%
Aspergillus niger	0	0,00%
Aspergillus versicolor	0	0,00%
Alternaria alternata	0	0,00%
Ulocladium chartarum	0	0,00%
Stachybotrys chartarum	0	0,00%
Chaetomium globosum	0	0,00%
Streptomyces	0	0,00%

The evaluation is based on the assumption that the test has been made correctly according to OBH's guide lines.



E: lab@obh-gruppen.dk

7189 Ásgarður, Garðabær sportshall, basketball, retractable spectator stands, 296

DNA tests may reveal whether there are microorganisms (mould) in dust originating from moisture damaged building materials or concealed water damages. Microbiologic material from concealed constructions may over time be released to the residential zone, where it will sediment with the dust. The result of the DNA analysis is an indication of the extent of which the room is affected by microbiologic material.

CONCLUSION

Based on the analysis results for the test made from sportshall, basketball, retractable spectator stands, Ásgarður, Garðabær, our evaluation is that the rate of mould in the building is somehow above the normal, expected level for dry, clean and undamaged buildings. The presence of *Aspergillus* and *Penicillium* often observed in buildings with moisture and water damages is far above normal level. There is an increased level of *Aspergillus versicolor and Aspergillus fumigatus* in the test.

As a whole our evaluation is that the zone is affected by atypical levels of microbiologic material.

However, we would like to point out that the evaluation is merely based on the analysis results. As the results only form part of our evaluation basis, these results should always be compared to observations and moisture measurings on site, before drawing a final conclusion. We therefore recommend further testing in order to identify extent and cause of the observed occurrence of mould and moisture problems in the inspected areas.



The mould level is normal, and there are no indications of concealed moisture damages.

Furthers actions are not necessary.

The mould level is slightly increased, which may indicate an old dried-out damage or cumulation of fungi material in dust.

Small renovations must be expected, or cleaning according to further instructions.

The occurrence of mould is abnormal, which indicates a severe and/or long-term water damage.

A big renovation work must be expected, which means to find and eliminate the source of moisture, to determine the extent of the damage and to draw up a plan of action for the renovation.



7189 Ásgarður, Garðabær sportshall, basketball, retractable spectator stands, 296

RESULT

Mængden af organismer pr. cm²

Total antal skimmelsvamp	8345	100,00%
Wallemia sebi	0	0,00%
Cladosporium cladosporioides	456	5,46%
Cladosporium herbarum	214	2,57%
Cladosporium sphaerospermum	73	0,88%
Mucor/Rhizopus grp.	0	0,00%
Rhizopus stolonifer	0	0,00%
Acremonium strictum	0	0,00%
Aspergillus og Penicillium arter	1887	22,61%
Aspergillus fumigatus	26	0,31%
Penicillium chrysogenum	0	0,00%
Tricoderma viride	0	0,00%
Aspergillus glaucus	0	0,00%
Aspergillus niger	8	0,10%
Aspergillus versicolor	772	9,25%
Alternaria alternata	92	1,11%
Ulocladium chartarum	0	0,00%
Stachybotrys chartarum	0	0,00%
Chaetomium globosum	0	0,00%
Streptomyces	0	0,00%

The evaluation is based on the assumption that the test has been made correctly according to OBH's guide lines.

Contact the undersigned regarding questions to the report

Med venlig hilsen

Tina Eckardt Laborant

OBH Rådgivende Ingeniører

Tina Eckarott

Environment and Health



E: lab@obh-gruppen.dk

ANALYSIS METHOD

The analysis was developed by EPA, USA's Environmental Protection Agency (pat 6 387 652). The organisms are washed out of the test, and the DNA is extracted. Accordingly, the DNA is amplified in a sequential PCR process, until the light from an attached fluorescence molecule can be seen in the detector. The number of sequences are calculated and compared to a synthetic standard DNA, after which the number of original DNA sequences are calculated. As the DNA is unique for any organism the species and quantity of specific organisms can be determined. By this precise method you will rapidly be informed how much mould, respective indicator organisms which the test contains per square unit.

ANALYSIS EXPLANATION

The above evaluation applies for the test made, and not for the building as such. The analysis response should always be included as part of a total evaluation of the conditions on site together with other observations and measurings. The responsibility for correct testing always lies with the tester. Evaluations and good advice given here or in connection with interpretation of these results apply for the normal cases and are based on the assumption that the test is representative and made according to OBH's guide lines.

TAKING A DUST TEST

The purpose of the test is to evaluate whether in the indoor air there are microorganisms to indicate moisture damaged building parts. Mould releases particles, spores, cells, and other fungus components containing DNA, to the air. These microparticles float in the air and are sedimented with dust in the living area. Collecting dust is thus an expression of whether the air of the room has been effected by particles from mould over an extended period of time.

INDICATION OF QUANTITY

The DNA analysis distinguishes between 20 groups/species.

The test result states the number of DNA sequences for respective species and groups per cm².

Any colour markup states the level of each species or group, deviating according to the levels of dry, clean and undamaged buildings.

Yellow Above normal
Orange Far above normal
Red Very far above normal



E: lab@obh-gruppen.dk

HEALTH

Mould in our indoor environment may affect our health, most commonly with respiratory irritation. Further symptoms are irritation of eyes, nose and upper respiratory tract, headache, fatigue, coughing, and rashing. These symptoms will be more severe for persons with hay fever and asthma. Asthmatic symptoms may occur in connection with a long-term stay in an indoor environment with massive mould problems. The DNA result does not reveal anything about the health risk of residing in the building.

THE HEALTH DAMAGING EFFECT

In order to evaluate the health risk of residing in a building, a construction technical and healthcare evaluation must be made. According to the Danish National Board of Health the health risk is among others characterized by the unhealthy circumstances as well as the moisture and mould conditioned health problems of the residents/users.

READ MORE

www.obh-gruppen.dk www.sst.dk www.astma-allergi.dk www.indeklimaportalen.dk

